

Improvement Opportunities Frequency Rate (IOFR) the Current Rolling IOFR is: **1.40**
(Target of 2.5 per 1000 hours worked)

Accident Frequency Rate (AFR) Days since the Last RIDDOR accident: **298**
The current rolling AFR is: **0.03**

Service Strike (SSFR) Days since the last Service Strike: **13**
The current rolling SSFR is: **0.35**

March
Total Number IOs
216

March
No. Safety, Health & Environmental IOs
N/A

March
No. Business IOs
N/A

Reference Number	Business unit	Date	Project	Description
Injury				
13392024-07-03	Highways	07/03/2024	CP 21SP10 Chiswick Flyover Concrete Repairs	Delivery driver dropped 3 GRP angles on supervisor's finger causing laceration
Operational Close Call				
13342024-06-03	Rail	06/03/2024	OTW AfA Farnborough North	Piling rig pushed platform block pavours and copers too close to track, resulting in 180 minutes of train delays
Service Strike – Electric				
13472024-18-03	Rail	18/03/2024	Gloucester Forecourt & Underpass Improvement Works	LV cable damaged by excavator bucket during excavation of leader trench
High Potential Near Miss/Close Call				
13322024-04-03	Rail	01/03/2024	OTW GEO Crewkerne Tunnel Refurbishment	RCM equipment blown over in high winds resulting in black alert
13312024-01-03	Highways	01/03/2024	NH SDF Area 12 NE Wentbridge Viaduct Waterproofing	10 cones knocked over by MOP when exiting chicane in TM
13362024-07-03	Highways	07/03/2024	NH SDF Area 12 NE Wentbridge Viaduct Waterproofing	Works lorry drove the wrong way on a one way system to enter the works – no damage or injuries
13402024-11-03	Highways	08/03/2024	NH SDF NW M56 J12-11	Works vehicle entered the closure early whilst it was still being established – no damage or injuries
13442024-12-03	Highways	11/03/2024	NH SDF Area 12 NE Wentbridge Viaduct Waterproofing	Works lorry drove the wrong way on a one way system to enter the works as they were late – no damage or injuries
Environment – Spillage				
13452024-13-03	Highways	13/03/2024	HS2 EKFB	Sub-contractor van sustained oil leak in site compound, contained and no lose to sensitive receptor
TM Incursion				
13382024-07-03	Highways	06/03/2024	NH SDF NW A66 Redhill Dual EB &	Driver of the car was coming down the A66 EB on 1 lane running, he has

			WB	admitted to not paying attention to the signs. Driven through a no entry sign and 3 cones and through the works access gates. Police were called, breathalysed him (passed) and issued him with a driving without due car and attention.
13412024-11-03	Highways	08/03/2024	NH SDF M56 J12-J11	Driver confused following sat nav and entered works' access. Escorted out.
13432024-12-03	Highways	12/03/2024	NH SDF M60 CW/ACW Road Marking Scheme	MOP stopped whilst driving through works at speed. Not clear why. Escorted from site.
13462024-15-03	Highways	15/03/2024	NH SDF NW A66 Redhills	MOP vehicle followed works vehicles into closure
13482024-18-03	Highways	15/03/2024	NH SDF M60 CW/ACW Road Marking Scheme	2 vehicles followed welfare vehicle into closure
13492024-20-03	Highways	19/03/2024	NH SDF M60 CW/ACW Road Marking Scheme	1 vehicle followed welfare vehicle into closure
13512024-21-03	Highways	20/03/2024	NH SDF NW M56 J12-J11	MOP entered closure to ask for directions
13542024-02-04	Highways	20/03/2024	NH SDF NW M56 J12-J11	MOP confused. Escorted through works.
Theft				
13332024-06-03	Rail	06/03/2024	OTW E&P Package 8 TRU's	Theft of cable from compound
13422024-11-03	Highways	11/03/2024	Cambridge Road, Harlow	Fencing cut through and storage container cut open, various items of plant stolen
13522024-25-03	Highways	25/03/2024	A46 Walsgrave	Attempted theft – broken lock on gate
Property Damage				
13372024-07-03	Highways	07/03/2024	NH SDF NW A66 Redhills	Vehicle being escorted through site overtook escort and collided with roller. Damaged tyre.
Other Classification				
13502024-20-03	Highways	01/03/2024	HS2 EKFB	Member of staff became locked in ECO unit toilet, door cut off to release